E - 000

CONVAIR

A THIRTHON OF SENERAL BYNAMICS - DEHODATION SAIL OIL TO, CALLEGRILLA

SPEC NO.: ZD- 22-323		D	ATE	
CUSTOMER. Alaska Ai	rlines Inc.	M	CL 13.014	DTD
CHANGE NO: 25		M	ODEL 22-21(#2) (Convair "880")
TITLE Specificat Hook)	ion Administrativ	e Chang	e (Revision t	o Lavatory Coat
ORIGIN Convair in	itiated			
REASON FOR CHANGE: TO	clarify the inte	nt of th	ne specificat	ion.
EFFECT O	ON WEIGHT .		EFFECT	ON BALANCE .
GUAR, WT. EMPTY	OPER. WT. EMPTY			
0	0			O INCH LB.
EFFECT ON GUARANTEED P	ERFORMANCE: None			
NEGLIGIBLE CHANGES WILL TOTALS REFLECTED IN A ACCEPTANCE OF THIS CHA PRIOR ACCEPTANCE OF THE	FUTURE CHANGE PROPOS ANGE IS DEPENDENT UPO	SAL M	Reach	7/24/61
			ENC	SINEERING APPROVAL
LATEST DATE OF ACCEPTA		AIRPL AN	ES AFFECTED:	
SPECIAL PROVISIONS		RECURRING NON-RECL	JRRING:	
ACCEPTED.			A DIVISION OF GENE	RAL DYNAMICS CORP.
BY-				
DATE:				Service Control

5-4-1

Alaska Airlines Inc. Change No. 25

Title: Specification Administrative Change (Revision to Lavatory

Coat Hook)

Origin: Convair initiated

Reason for Change: To clarify the intent of the specification.

Description of Change:

Page 87, Paragraph 3.19.2.2.3 MISCELLANEOUS LAVATORY EQUIPMENT:

Revise below item as follows:

From: "One coat hook (folding-type on lavatory door)"

To: "One coat hook"

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None

A DIVISION OF GENERAL DYNAMICS CORPORATION SAN DIEGO, CALIFORNIA

SPEC NO.: ZD-22-323			DATE:
CUSTOMER: ALASKA AIR	LINES INC.		MCL 13,013 DTD
CHANGE NO; 24			MODEL: 22-21 (#2) (Convair "880
TITLE: Specificat 3.2.2.1)	ion Administrative	Chan	ge (Revision to Paragraph
ORIGIN: Convair in	itiated		
REASON FOR CHANGE:	Specification cla	rific	ation.
EFFECT	ON WEIGHT *		EFFECT ON BALANCE *
GUAR, WT. EMPTY	OPER, WT. EMPTY		
0	0		O INCH LB.
EFFECT ON GUARANTEED F	PERFORMANCE: * Non	ie .	
ACCEPTANCE OF THIS CH	L BE ACCUMULATED AND FUTURE CHANGE PROPOSE ANGE IS DEPENDENT UPOTHE FOLLOWING CHANGES:	SAL	ENGINEERING APPROVAL
LATEST DATE OF ACCEPTA	NCE:	AIRPL	ANES AFFECTED:
SPECIAL PROVISIONS:		RECUR NON-R	CT ON PRICE PER AIRPLANE: RRING: ECURRING:
ACCEPTED:		CONVA	AIR, A DIVISION OF GENERAL DYNAMICS CORP.
DATE:			-0NVAHIC. D. 6-1217A

Alaska Airlines Inc. Change No. 24

Title: Specification Administrative Change (Revision to Paragraph

3.2.2.1)

Origin: Convair initiated

Reason for Change: Specification clarification.

Description of Change:

Page 9, Paragraph 3.2.2.1 COLOR CODING:

Revise the paragraph as follows:

Prom: "COLOR CODING: All sections of plumbing shall be color coded and banded in accordance with Military Standards and, in addition, marking shall indicate the direction of flow and the purpose of the line. The part number of each tubing assembly shall be identified. Color bands and part number identifications shall be plastic tape in accordance with Standard AND 10375."

To: "COLOR CODING: All sections of plumbing, except engine and within fuel tanks, shall be color coded and banded. All plumbing shall indicate the direction of flow and the purpose of the line. The part number of each tubing assembly shall be identified. Color bands shall be plastic tape in accordance with Standard AND 10375."

Effect on Weight Empty: 0 Effect on Balance: 0 Effect on Performance: None

A DITIMOT OF SERVICAL DYNAMICS CORPORATION SALECTESO, CALIFORNIA

SPEC NO. 20- 41-343			DATE			
CUSTOMER Alaska Ai	rlines Inc.		MCL 1	3,075	. DTD_	
CHANGE NO. 23			MODEL:	22-21	(#2)	(Convair "880
	ion of Inflatable e Escape Chutes	Escap	e Chut	es in]	ieu of	Non-
ORIGIN Customer	request	•				
REASON FOR CHANGE A	s above					
EFFECT	ON WEIGHT			EFFE	CT ON BA	LANCE .
GUAR, WT. EMPTY	OPER. WT. EMPTY					
+60.0 lb	+103.0 lb			+ +8	30,958	INCH LB.
EFFECT ON GUARANTEED I	PERFORMANCE: '					
	None		,			
* NEGLIGIBLE CHANGES WILL BE ACCUMULATED AND TOTALS REFLECTED IN A FUTURE CHANGE PROPOSAL ACCEPTANCE OF THIS CHANGE IS DEPENDENT UPON PRIOR ACCEPTANCE OF THE FOLLOWING CHANGES						Lealy 61, 1,
					NGINEER	ING APPROVAL
LATEST DATE OF ACCEPTA	ANCE:	AIRPL	ANES AFI	ECTED:		
R		EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING: TOTAL:				
ACCEPTED		CONVA	IR, A DIVI	SION OF GE	NERAL DY	'NAMICS CORP.
BY						
686						

Alaska Airlines Inc. Change No. 23

Title:

Installation of Inflatable Escape Chutes in lieu of Non-

Inflatable Escape Chutes

Origin:

Customer requested

Reason for Change: As above

Description of Change:

Page 95, Paragraph 3.19.6.2 EVACUATION PROVISIONS:

Change the first sentence to read as follows:

"Suitable means shall be provided for assisting rapid evacuation from emergency exits including escape ropes at exits over the wing and in the pilot compartment, and inflatable escape chutes at other emergency exits.

Page A-15, APPENDIX I-C - FURNISHINGS:

Change the fifth item in the equipment list as follows:

"4* Escape Chute (Noninflatable) From:

65.0"

"4* Escape Chute (Inflatable) To:

108.0"

Effect on Weight Empty: +60.0 pounds Effect on Operating Weight Empty: +103.0 pounds
Effect on Operating Weight Empty Balance: +80,958 inch-pounds

Effect on Performance: None

A 19 PERIOD OF GENERAL DYNAMICS COREGNATION SAN DIEGO-CALIFORNIA

SPEC NO ZD 22-323		DAT	E			
CUSTOMER. Alaska Air	lines Inc.	MCL	13,012	DTD_		
CHANGE NO: 22		MOD	DEL: 22-21	(#2)	(Convair	"880"
TITLE. Specifica cator Lig	tion Administrativ	ve Change	(Landing	Gear !	Pin Indi-	
ORIGIN Convair 1	nitiated	and the second s				
REASON FOR CHANGE: TO	specify that subj	ect indi	cator lig	hts are	e install	ed.
EFFECT	ON WEIGHT .		EFFE	CT ON BA	LANCE .	
GUAR, WT. EMPTY	OPER. WT. EMPTY					HE V
0	0			0	INCH	LB.
EFFECT ON GUARANTEED P	ERFORMANCE .					
	None		angunium unudak saran			
* NEGLIGIBLE CHANGES WIL TOTAL 5 REFLECTED IN A ACCEPTANCE OF THIS CHAPRIOR ACCEPTANCE OF T	FUTURE CHANGE PROPOS ANGE IS DEPENDENT UPOR	N ME	V	Ma	HH,	AL
LATEST DATE OF ACCEPTA	NCE:	AIRPLANES	AFFECTED:			
SPECIAL PROVISIONS:		RECURRING NON-REGUR	PRICE PER A			
ACCEPTED:		CONVAIR, A	DIVISION OF G	ENERAL D	YNAMICS CORP	
BY-						
DATE:					No Standard	10.451/19

Alaska Airlines Inc. Change No. 22

Title: Specification Administrative Change (Landing Gear Pin

Indicator Lights)

Origin: Convair initiated

Reason for Change: To specify that subject indicator lights are

installed.

Description of Change:

Page 21, Paragraph 3.8.1.5 LANDING GEAR SAFETY LOCK PINS:

Add the following to the end of the paragraph:

"Indicator warning lights shall be provided in the flight engineer's panel and shall be illuminated when the "safety lock" pins are inserted in the gear."

Effect on Weight Empty: 0 Effect on Balance: 0 Effect on Performance: None

TATE DESCRIPTION OF A PROPERTY OF A PROPERTY

			DATE				
CUSTOMER Alaska Ai	rlines Inc.		MCL 13	073	DTD_	1 March 19	51
CHANGE NO 21			MODEL	22-21	(#2)	(Convair	1880
TITLE Main Tires,	Fabric Reinforce	d, In	stallati	on of			
ORIGIN: Convair ini	tiated						
REASON FOR CHANGE:	Product improveme	nt					
					and distance and the same and t		
	DN WEIGHT "			EFFEC	T ON BA	LANCE .	
GUAR, WT. EMPTY	OPER. WT. EMPTY						
+23.0 16	+23.0 lb			+21	0,194	INCH L	В.
EFFECT ON GUARANTEED P	PERFORMANCE: None						
* NEGLIGIBLE CHANGES WILL TOTALS REFLECTED IN A ACCEPTANCE OF THIS CHA PRIOR ACCEPTANCE OF T	FUTURE CHANGE PROPOS ANGE IS DEPENDENT UPO	SAL N	>	. e	<i>GL</i>	3/30/6 INC APPROVAL	,
LATEST DATE OF ACCEPTA	NCE.	AIRPLA	ANES AFFE	CTED.			
SPECIAL PROVISIONS:		EFFECT ON PRICE PER AIRPLANE. RECURRING, NON-RECURRING; TOTAL:					
			R, A LIVISIO			NAMICS CORP.	
BY:							
DATE:						e value its	7:4:

CONVAIR: SD

Title: Main Tires, Fabric Reinforced, Installation

Origin: Convair initiated

Reason for Change: Product improvement

Description of Change:

Page A-14, APPENDIX I-C, LANDING GEAR EQUIPMENT:

Revise the below item under "Description" as follows:

From: "8 Tire, Main Wheel (39 x 13) Type VII 22 Ply Rating, Skid Depth .25-inches)

U.S. Rubber"

"8 Tire, Main Wheel (39 x 13) To: (Type VII, 22-Ply Rating, Fabric-Reinforced Tread, Skid Depth .35-inch)

U.S. Rubber"

Effect on Weight Empty: +23.0 pounds

Effect on Balance: +20,194 inch-pounds Effect on Performance: None

6 PERCHAPARA CONAMINATION TO CATOON

SPEC NO. ZD-22-323		DATE	
CUSTOMER Alaska Airlines Inc.		MCL 13,074 DID 3 March 196	1
CHANGE NO 20		MODEL 22-21(#2) (Convair "88	0")
Tape Reproducer, Inst	allation of	r'	
ORIGIN Verbal request, Sindt	to Carothe	ers, 2 March 1961	
REASON FOR CHANGE Customer requ	est		
		ngin and deliver between the control of the control	
EFFECT ON WEIGHT		EFFECT ON BALANCE *	
GJAR, WT. EMPT			
+23.0 lb +23.	0 lb	+6,049 INCH L	В.
EFFECT ON GU-RANTEED PERFORMANCE .			
	None		To.
* NEGLIGIBLE CHANGES WILL BE ACCUMULATED TOTALS REPLECTED IN A FUTURE CHANGE		a 1 to 21 1 1	(18)
ACCEPTANCE OF THIS CHANGE IS DEPENDE PRIOR ACCEPTANCE OF THE FOLLOWING C		potende of 3/4h, Mi	9
		ENGINEERING APPROVAL	
LATEST DATE OF ACCEPTANCE:	AIRPL	ANES AFFECTED	
Andrew Commission of the Commi		futballing shallpysh a sugar, one the state of the same of a month of the same	
SPECIAL PROVISIONS		CT ON PRICE PER AIRPLANE	
	NON-K	RING: CURRING:	
	TATEL		
ACCEPTED		JR, A DIVISION OF SEMERAL DYNAMICS CORP.	3
BY			
DATE			

CONVAIR: SD

Title: Tape Reproducer, Installation of

Origin: Verbal request, Sindt to Carothers, 2 March 1961.

Reason for Change: Customer request.

Description of Change:

Page 71, Paragraph 3.17.1 EQUIPMENT:

Add the following item under "Description":

"Airborne Tape Reproducer"

Delete the below item under "Provisions for the following systems shall be made":

"Airborne Tape Reproducer"

Page 79, Paragraph 3.17.2.3.6 PUBLIC ADDRESS SYSTEM:

Revise the third sentence as follows:

From: "The system shall include provisions for an airborne tape reproducer located in the radio rack."

To: "The system shall include the installation of an airborne tape reproducer in the radio rack."

Page A-10, APPENDIX I-C, ELECTRONIC EQUIPMENT:

Add the following item under "P.A. SYSTEM":

"1 Airborne Tape Reproducer Gables G-825"

Effect on Weight Empty: +23.0 pounds

Effect on Balance: +6,049 inch-pounds

Effect on Performance: None

A DIVISION OF GENERAL DYNAMICS COMPORATION SAN DIE 40. CALIFORNIA

SPEC NO. 20- 22-323			DATE:			
CUSTOMER. Alaska Air	lines Inc.		MCL 13,071	DTD 10) Febru	ary 196
CHANGE NO: 18A		•	MODEL . 22-21(;	#2) (Cd	onvair	"880")
THILE Passenger So	eating Configurati	Lon, Cl	nange to			
and Alaska ary 1961 (W		to R.	B. Carother	s, dated	d 10 Fe	
REASON FOR CHANGE C	ustomer request, a	and re	vision to CC	P NO. IC	o .	
EFFECT	ON WEIGHT .		EFFE	CT ON BAL	ANCE *	
GUAR, WT. EMPTY	OPER. WT. EMPTY					
+7 44. 0 1b	+785.0 lb		+691,5	18	IN	ICH LB.
EFFECT ON GUARANTEED P	ERFORMANCE, * None					Sil
NEGLIGIBLE CHANGES WILL TOTALS REFLECTED IN A ACCEPTANCE OF THIS CHAPPEIOR ACCEPTANCE OF T	FUTURE CHANGE PROPOS ANGE IS DEPENDENT UPO	SAL	V	Dung ENGINEERIN		
LATEST DATE OF ACCEPTA	NCE.	AIRPLA	NES AFFECTED:	Mointer		W
SPECIAL PROVISIONS.		RECURE NON-RE	F ON PRICE PER ARING CURRING			
ACCEPTED		CONVAI	R, A DIVISION OF G	ENERAL DY	NAMICS CO)RP.
BY:						
DATE:	PROPORTINA				HARVEY IN	40 6 F2 FA

Alaska Airlines Inc. Change No. 18A

Page 1 of 5

Title: Passenger Seating Configuration, Change to

Origin: Verbal request, George Sindt to D. H. Digges on 9 February

1961; and Alaska TWX, George Sindt to R. B. Carothers,

dated 10 February 1961 (WUA069)

Reason for Change: Customer request, and revision to CCP No. 18.

Description of Change:

Page 1, Paragraph 1.1 BASIC TYPE:

Revise the second and third sentences to read as follows:

"This specification describes an interior and seating arrangement for the accommodation of 107 passengers; consisting of 95 coach passengers and 12 lounge area passengers. Provisions also are incorporated in this airplane to permit conversion to various mixed seating arrangements and to a full first class seating arrangement."

Page 3b, INTERIOR ARRANGEMENT:

Replace the above illustration with Enclosure (A) which shows an all coach seating arrangement in lieu of first class seating; with the lounge area remaining unchanged.

Page 6, Paragraph 3.1.2.2 TYPICAL LOADING SUMMARY:

Under "Manufacturer's Weight Empty (dry)", change "(Standard Configuration)" to "(Coach Configuration, with 12-Place Lounge)".

In "Fixed Useful Load", change "Life Vests (91)" to "Life Vests (114)".

In "Payload (space limit)*, delete the asterisk and change "(Standard Configuration)" to "(Coach Configuration, with 12-Place Lounge)".

Revise "Space Limit Payloads: " as follows:

From:	"Space Limit Payloads:	Standard	Coach Configuration
	Passengers @ 165 lb (84 standard)(105 alter- nate coach)* Baggage @ 40 lb/passenger Cargo	13,860 3,360 5,270 22,490	17,325 lb 4,200 lb 4,430 lb 25,955 lb

Alaska Airlines Inc. Change No. 18A

Page 2 of 5

To: "Space Limit Payloads:

Coach Configuration with 12-Place Lounge

Passengers @ 165 lb (95 coach and 12-lounge) Baggage @ 40 lb/passenger Cargo

4,280 lb 4,350 lb 26,285 lb

17,655 lb

Delete the asterisk note on the bottom of Page 6 "(*NOTE: Space limit coach arrangement of)"

Page 9, Paragraph 3.2.1 GENERAL INTERIOR ARRANGEMENTS:

Revise the first sentence as follows:

From: "The standard interior arrangement of this airplane shall be as shown on the inboard plan and profile drawing."

To: "The interior arrangement of this airplane shall be as' shown on Page 3b - INTERIOR ARRANGEMENT."

Page 16, Paragraph 3.7.1.3 CREW AND PERSONNEL STATIONS:

Revise the sentence as follows:

From: "The interior arrangement for the standard configuration shall be essentially as shown on the Inboard Profile Drawing herein."

To: "The interior arrangement shall be essentially as shown on Page 3b - INTERIOR ARRANGEMENT."

Page 63, Paragraph 3.16.8.3.4 READING LIGHTS:

Delete the second and third sentences which read as follows:

"Of the five lights provided at each passenger seat row, four shall be installed in optimum direction for the four-abreast standard seating arrangement. The fifth shall be directed toward the center coach seat location."

Delete the last seven words in the fourth sentence "(and placard to clearly indicate its function)"

Alaska Airlines Inc. Change No. 18A

Page 3 of 5

Page 79, Paragraph 3.17.2.3.7 SPEAKERS:

In the second line, delete the word "standard".

Page 82, Paragraph 3.19.1 GENERAL:

Revise the paragraph to read as follows:

"The interior shall include furnishings and equipment for 107 passengers (including 12 lounge area passengers) and crew accommodations as shown on illustration herein. In addition, the interior shall be designed to permit conversion to various mixed seating arrangements and to a full first class seating arrangement."

Page 84, Paragraph 3.19.1.1.6 PASSENGER SEATS:

Revise the paragraph to read as follows:

"The passenger seating arrangement shall be as shown on Page 3b -INTERIOR ARRANGEMENT: consisting of 19 double coach seats, 19 triple coach seats and a 12-place lounge area. All passenger seats, except lounge seats, shall have reclinable backs and shall be equipped with plug-in center arm rests in the double seats, and with plug-in arm rests in the triple seat assembly except for the inboard and outboard arm rests which shall be fixed. Stowage provisions for life vests shall be made on the underside of the passenger seats. Integral folding food trays shall be installed in the passenger seat backs excluding last row of seats and the seats immediately forward of the movable coat dividers which shall have provisions only. Plug-in food trays shall be provided for the five front row seats, the five seat places just aft of the movable coat dividers and the 12place lounge seats. Stowage for plug-in trays shall be provided. Literature pockets shall be installed on the main cabin forward partitions, the aft side of the movable coat dividers and directly below the food trays in the passenger seat backs."

Page 84, Paragraph 3.19.1.1.6.1 SEAT BACK MOVEMENT:

Revise the paragraph to read as follows:

"Each reclining seat shall be designed so that pressure applied on the aft side of the seat back will override the recline control lock without additional manual operation, and fold the seat back forward to its normal upright position. This pressure on the seat back shall not exceed 25 pounds. The seat back shall

Alaska Airlines Inc. Change No. 18A

Page 4 of 5

fold to approximately 30 degrees forward of the vertical position by applying a load of not less than 30 pounds, or more than 35 pounds, at the top of aft side of the seat back without removing the center arm rest. The seat back may be further folded to approximately a horizontal position by removing the center arm rest. Seat back positions shall be as follows:

Normal Upright: 15 degrees aft of vertical

Maximum Recline: 38 degrees aft of vertical"

Delete the note on the bottom of Page 84 which reads:

"*45 degrees seat recline restricts use of integral folding food trays."

Page 89, Paragraph 3.19.3.1 GENERAL ARRANGEMENT:

In the first line, delete the word "standard".

Page 89, Paragraph 3.19.3.1.1 PASSENGER COMPARTMENT:

Revise the first sentence as follows:

From: "The main passenger compartment aisle shall be a minimum of 24 inches wide between arm rests in the standard configuration."

To: "The main passenger compartment aisle width shall be approximately 19 inches between arm rests in the coach configuration."

Page 91, Paragraph 3.19.3.6 HAT RACKS:

In the last line, change "Standard" to "Coach".

Page 94a, GASEOUS OXYGEN SYSTEM:

Above illustration will be revised to show 23 seat rows in lieu of 22."

Page A-2, APPENDIX I-B, CUSTOMER FURNISHED - CUSTOMER INSTALLED:

Revise the below item under "Description" as follows:

Alaska Airlines Inc. Change No. 18A

Page 5 of 5

"91 Life Vest From:

159.0"

"114 Life Vest To:

200.0"

Page A-15, APPENDIX I-C, FURNISHINGS:

Revise the below items under "Description" as follows:

"36 68 From: Seats, Double (First Class)

Tray, Integral Folding Food

Tray, Plug-in Type 20

Belt, Passenger Safety"

To:

- "16 Double Seat Assemblies, R.H. TE-801-T-2-44
 - Teco Inc.
 Teco Inc. Triple Seat Assemblies, L.H. 16 TE-801-T-3-64
 - Triple Seat Assemblies, L.H. Teco Inc. TE-801-T-3-64B Special
 - Double Seat Assemblies, R.H. Teco Inc. TE-801-T-2-44B Special
 - 1 Triple Seat Assembly, L.H. Teco Inc. TE-801-TC-3-64 Special
 - Double Seat Assembly, R.H. Teco Inc. TE-801-TC-2-44 Special
 - 85 Trays, Integral Folding Food
- Trays, Plug-in Type 22
- Belts, Passenger Safety" 107

Add the following item to the "Description List":

"19 Removable Plug-in Tables

Teco Inc. 6574"

Enclosure: (A) One copy Page 3b - INTERIOR ARRANGEMENT (Revised)

Effect on Weight Empty:

+744.0 pounds

Effect on Weight Empty Balance:

+655,602 inch-pounds

Effect on Operating Weight Empty: Effect on Operating Weight Empty: +785.0 pounds
Effect on Operating Weight Empty Balance: +691,518 inch-pounds

Effect on Performance: None


The following shall not appear in the specification language:

The installation of the coach seats as covered by this proposal will be at 36-inch spacing, except that the five seat rows immediately aft of movable coat dividers will be at 35-inch spacing.

A "Babe in Arms" placard will be installed on the forward left hand partition.

Total weight of complete seats (including seat belts), 19 triple coach seats and 19 double coach seats, must not exceed 3,002 pounds. If actual weight exceeds this weight, the difference shall be Customer responsibility.

4.8



INTERIOR ARRANGEMENT
95 COACH PASSENGERS
17 PLACE LOUNGE AREA
ALASKA

STA 3.47

A DIVISION OF GENERAL DYNAMICS CORPORATION SAN DIEGO, CALIFORNIA

SPEC NO.: ZD- 22-323		DA'	TE:	-3		
CUSTOMER: Alaska Air	MCL 13,011 DTD					
CHANGE NO: 17		MOI	DEL: 22-21	(#2) (Cc	nvair "88	0")
TITLE: Specificat Improvemen	ion Administrative t Changes)	Change	(Miscellar	neous Des	ign	
ORIGIN: Convair in	itiated				2 2	
REASON FOR CHANGE:	Product improvemen	nt				
EFFECT (ON WEIGHT *		EFFE	CT ON BALA	NCE *	
GUAR. WT. EMPTY	OPER. WT. EMPTY					
0	0			0	INCH LB	•
EFFECT ON GUARANTEED F	PERFORMANCE: * None		S			1131
* NEGLIGIBLE CHANGES WIL TOTALS REFLECTED IN A ACCEPTANCE OF THIS CH PRIOR ACCEPTANCE OF T	FUTURE CHANGE PROPOSE ANGE IS DEPENDENT UPO	SAL N	garte	WY D	GAPPROVAL	
LATEST DATE OF ACCEPTA	NCE:	AIRPLANE	S AFFECTED:			
SPECIAL PROVISIONS:		RECURRING NON-RECUR	N PRICE PER A G: RRING:		Vii = 15	
ACCEPTED:	41	CONVAIR, A	DIVISION OF GE	ENERAL DYNA	MICS CORP.	
BY:						
DATE:				c	ONVAIR,5.D. 6-121	17A

Alaska Airlines, Inc. Change No. 17

Page 1 of 2

Title:

Specification Administrative Change (Miscellaneous Design

Improvement Changes)

Origin:

Convair initiated

Reason for Change: Product improvement

Description of Change:

Page 3a. CENERAL ARRANGEMENT:

Replace above illustration in the specification with Enclosure (A) which shows Krueger Flap installation between inboard pylon and fuselage, and trailing edge inboard flap extension.

Page 25, Paragraph 3.10.1.3 RUDDER SYSTEML

Insert the following sentence after the third sentence:

"In addition a hydraulically-operated servo unit powered from one hydraulic system shall be installed in the pedal linkage, in the nose wheel well, to reduce rudder pedal forces.

Page 26, Paragraph 3.10.2.1 LIFT AND DRAG INCREASING DEVICE SYSTEMS:

Delete the paragraph and substitute the following:

"LIFT AND DRAG INCREASING DEVICE SYSTEMS: The trailing edge flaps and leading edge slats and flaps shall be operated by hydraulic power controlled by a single lever on the pilot's pedestal. The leading edge slats and flaps shall be operated through torque tubes from a gear box which is powered by two hydraulic motors, one motor connected to each hydraulic system. The trailing edge flaps shall be operated through torque tubes from a gear box which is powered by either of two motors, one motor connected to each hydraulic system. By means of "no-back" type devices incorporated in the screw jacks, each control system shall be irreversible to prevent flap motion from airload. Full trailing edge flap deflection and leading edge slat and flap extension shall be obtainable from either hydraulic system. A monitoring system shall be provided to produce asymmetrical positioning of the trailing edge flap in the event of mechanical failure. A pair of lights, one amber and one green, shall be installed on the center instrument panel for each right and left hand set of leading edge devices (slats and flaps). Lights shall illuminate "green" when the devices have fully extended and shall illuminate "amber" while the devices are in transit."

Alaska Airlines, Inc. Change No. 17

Page 2 of 2

Page 50a, HYDRAULIC SYSTEM:

Replace the above illustration in the specification with Enclosure (B) which shows 100 percent flap power available from either No. 1 or No. 2 Systems, rudder pedal boost and deletes "TEMP. CONTROL" callout.


Enclosure: (A) One copy Page 3a - GENERAL ARRANGEMENT (Revised)

Enclosure: (B) One copy Page 50a - HYDRAULIC SYSTEM (Revised)

Rffect on Weight Empty: 0 Rffect on Balance: 0 Rffect on Performance: None

GENERAL ARRANGEMENT

Page 50a Report No. ZD-22-323 Model 22M



THE THE OF THE FEAT CONTRACTOR AS TO SELECT A CONTRACTOR AS TO SELECT A CONTRACT A CONTR

SPECING: 10-22-323		1.	JATE		
CUSTOMER Alaska Ai	irlines Inc.	4	13,010	DTD	
CHANGE NO. 16			MODEL.22-21	(#2) (Co	nvair "880")
	lcation Administrat ack Movement)	ive Ch	ange (Revis	sion to Pa	ssenger
ORIGIN: Convair	? initiated				
	Fo make specificatioack positioning ca			e with act	ual seat
EFFECT	ON WEIGHT .		EFF	ECT ON BALA	NCE .
SUAR, WILLMPTY	OPER, WT. EMPTY				
0	0			0	INCH LB.
EFFECT ON GUARANTEED	PERFORMANCE . None	· · · · ·			
TOTALS REFLECTED IN ACCEPTANCE OF THIS C	ILL BE ACCUMULATED AND A FUTURE CHANGE PROPO HANGE IS DEPENDENT UPO THE FOLLOWING CHANGES	SAL	Jul	Way ?	
LATEST DATE OF ACCEPT	ANCE	AIRPLA	NES AFFECTED		
		EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING TOTAL:			
ACCEPTED	employ of a depolar and the second	CONVAL	R, A DIVISION OF	ENERAL DYNA	AMICS CORP.
6Y					
DATE.					or at a mark

CONVAIR: SD Alaska Airlines Inc. Change No. 16

Title: Specification Administrative Change (Revision to Passenger

Seat Back Movement)

Origin: Convair initiated

Reason for Change: To make specification language agree with actual

seat back positioning capability.

Description of Change:

Page 84, Paragraph 3.19.1.1.6.1 SEAT BACK MOVEMENT:

Revise the paragraph to read as follows:

"Each reclining seat shall be designed so that pressure applied on the aft side of the seat back will override the recline control lock without additional manual operation, and fold the seat back forward to its normal upright position. This pressure on the seat back shall not exceed 25 pounds. The seat back shall fold to approximately 30 degrees forward of the vertical position by applying a load of not less than 30 pounds, or more than 35 pounds, at the top of aft side of the seat back without removing the center arm rest. The seat back may be further folded to approximately a horizontal position by removing the center arm rest. Seat back positions shall be as follows:

Normal Upright: 15 degrees aft of vertical

Normal Recline: 38 degrees aft of vertical (With integral

folding food trays installed)

Maximum Recline: 45 degrees aft of vertical (With integral folding food trays not installed)

Delete the note on the bottom of Page 84 which reads:

"*45 degrees seat recline restricts use of integral folding food trays."

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None



A DIVISION OF GENERAL DYNAMICS CORPORATION SAN DIEGO, CALIFORNIA

SPEC NO.: ZD- 22-323			DATE:
CUSTOMER: Alaska Air	lines Inc.		MCL 13,009 DTD
CHANGE NO: 14			MODEL: 22-21(#2) (Convair "880"
TITLE: Specification 3.10.1.5.1 a		Change	e (Revision to Paragraphs
ORIGIN: Convair init	iated		
REASON FOR CHANGE: To	clarify the inte	nt of	subject paragraphs
FFFECT (ON WEIGHT *		EFFECT ON BALANCE *
GUAR. WT. EMPTY	OPER. WT. EMPTY	,	
0	0		O INCH LB.
EFFECT ON GUARANTEED F	PERFORMANCE: * None		
* NEGLIGIBLE CHANGES WIL TOTALS REFLECTED IN A ACCEPTANCE OF THIS CH PRIOR ACCEPTANCE OF T	FUTURE CHANGE PROPOS ANGE IS DEPENDENT UPO	SAL N	Attory of 61, ENGINEERING APPROVAL
LATEST DATE OF ACCEPTA	NCE:	AIRPL	ANES AFFECTED:
SPECIAL PROVISIONS:		RECUR NON-RE	CT ON PRICE PER AIRPLANE: RRING: ECURRING:
ACCEPTED:		CONVA	AIR, A DIVISION OF GENERAL DYNAMICS CORP.
BY:			
DATE:			$\mathcal{D} = V + I \cdot (1 + 1) + G + I \cdot A$

Title: Specification Administrative Change (Revision to Paragraphs

3.10.1.5.1 and 3.11.8)

Origin: Convair initiated

Reason for Change: To clarify the intent of subject paragraphs.

Description of Change:

Page 26, Paragraph 3.10.1.5.1 - STABILIZER TRIM CONTROL:

Delete the last two sentences and substitute the following

"A switch, guarded in the on position, shall be installed on the pedestal to shut off all hydraulic power to the stabilizer screw jack. A three-position momentary switch shall be installed on the pedestal which, after the hydraulic shutoff switch is moved to "OFF", operates the standby electrical-mechanical stabilizer trim control. In addition, hand cranks shall be installed on the pedestal for emergency manual stabilizer trim control".

Page 28, Paragraph 3.11.8 - INSPECTION AND MAINTENANCE:

Delete the last sentence and substitute the following:

"Each engine QEC (quick engine change build-up) shall be interchangeable and replaceable as a complete assembly, except for reverser cascades, and certain accessories which may not be required on individual installations".

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None

A THIS OF SENERAL BYNAMICS CORPORATION SAN GIUSD, CAUIFORINA

SPEC NO. 20- 22-323			DATE:			
CUSTOMER Alaska A1	rlines Inc.		MCL 13.0	069	DTD 20	ised January 196
CHANGE NO. 15						air "880")
HILE Navigator	's Station, Provi	sions	and Loo	se Equ	ipment f	or
ORIGIN Aleska A1 on 6 Janu	rlines verbal requary 1961	uest (Sindt to	o Caro	thers)	
REASON FOR CHANGE:	Customer request					
EFFECT	ON WEIGHT '			EFFEC	T ON BALA	NCE *
GUAR. WT EMPTY +10.0 lbs.	OPER. WT. EMPTY +10.0 lbs.			42,	942	INCH LB.
EFFECT ON GUARANTEED P	ERFORMANCE None		m.Le.			
NEGLIGIBLE CHANGES WILL TUTALS REFLECTED IN A ACCEPTANCE OF THIS CHA PRIOR ACCEPTANCE OF T	FUTURE CHANGE PROPO ANGE IS DEPENDENT UPO	SAL N	AT.	tleas	IGINE ERING	3/6/ APPROVAL
LATEST DATE OF ACCEPTA	NCF:	AIRPL	ANES AFFE	CTED:		
SPECIAL PROVISIONS:		EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING: TOTAL:				
ACCEPTED:	an a	CONVA	IR, A DIVISIO	N OF GEN	ERAL DYNAM	MICS CORP.
BY:						
BATE:					11 1 22	1002111. B 10.12.17A

Page 1 of 4

Title: Navigator's Station, Provisions and Loose Equipment for

Origin: Alaska Airlines verbal request (Sindt to Carothers)

on 6 January 1961.

Reason for Change: Customer request

Description of Change:

Page 16, Paragraph 3.7.1.3.1 - PILOT COMPARTMENT:

Add the following sentence to the end of paragraph:

"The observer's seat shall be interchangeable with a navigator's seat. (See Paragraph 3.19.1.1.3.1)

Page 72, Paragraph 3.17.1.1 - CONTROL PANELS:

Add the following items to the "Control Panel" Description List:

"*Audio Selector (1), Navigator Station
*Microphone Selector (1), Navigator Station".

Add the following to the bottom of Page 72:

"# Loose equipment"

Page 78, Paragraph 3.17.2.3.1 - AUDIO SELECTOR:

Add the following sentence, after the third sentence:

"In addition, an audio selector panel shall be provided as loose equipment for use at navigator station, when that station is installed".

Add the following sentence to the end of the paragraph:

"Microphone and headset jacks and necessary connectors shall be provided as a part of the harmesses for use at navigator station, when that station is installed".

Page 79, Paragraph 3.17.2.3.5 - SMOKE AND OXYGEN MASK AND MICROPHONE:

Add the following sentence after the first sentence:

"An oxygen mask with microphone shall be provided as loose equipment for use at navigator station, when that station is installed".

Page 2 of 4

Page 83, Add the following new paragraph to the page after Paragraph 3.19.1.1.3:

- 3.19.1.1.3.1 NAVIGATOR'S STATION (PROVISIONS): A navigator's seat, designed to be interchangeable with the observer's seat, shall be furnished as loose equipment. The following additional equipment shall be provided as loose equipment for alternate installation of a navigator station in lieu of an observer station:
 - a. Table, with light and stowage provisions for oxygen mask, and smoke mask
 - b. Safety belt

In addition, a navigator's console shall be installed for mounting the following items which shall be provided as loose equipment:

- Oxygen mask and regulator
- (2)Audio selector panel
- 3) Microphone and headset
- Microphone select panel
- Lighting control panel

Page 94, Paragraph 3.19.5.4 - INDIVIDUAL OUTLETS:

Add the following sentence after the first sentence:

'Provisions shall be made in the crew oxygen system for a navigator oxygen outlet, which shall be blanked off when not in use".

Page 94a, GASEOUS OXYGEN SYSTEM:

Replace above illustration in the specification with Enclosure (A) which shows provisions for a navigator mask and regulator.

Page A-10, APPENDIX I-C, ELECTRONIC EQUIPMENT:

Add the following items under "INTERPHONE SYSTEM (FLIGHT):

"*1 Microphone (Nav.) *1 Headphone (Nav.)

Telephonics Telex

RS-38E

Page 3 of 4

Add the following to the bottom of Page A-10:

"*Loose Equipment"

Page A-11, APPENDIX I-C, ELECTRONIC EQUIPMENT:

Add the following item under "Control Panels":

"* 1 Audio Selector Panel (Nav.)

Gables

G-551

Add the following to the bottom of Page A-11:

"*Loose Equipment"

Page A-15, APPENDIX I-C, FURNISHINGS:

Add the following items under "Description":

"**1 Table, with Light (Nav.)

**1 Seat, with Safety Belt (Nav.)
**1 Lighting Control Panel (Nav.)"

Add the following to the bottom of Page A-15:

"##Loose Equipment"

Page A-16, APPENDIX I-C, OCYGEN EQUIPMENT:

Add the following items under "Description""

"##1 Regulator (crew diluter demand-type) (Nav.)

**1 Supplemental Oxygen Mask (Nav.)

**1 Smoke Mask (Nav.)

Scott"

Type A-14

Add the following to the bottom of Page A-16:

"##Loose Equipment"

Enclosure: (A) One copy Page 94a - GASEOUS OXYGEN SYSTEM (Revised)

Effect on Weight Empty: +10.0 lbs.

Effect on Balance: +2,942 in. 1bs.


Effect on Performance: None

Alaska Airlines Inc. Change No. 15

Page 4 of 4

The following shall not appear in the specification language:

The loose equipment items defined in this proposal are provided for installation at Customer option, therefore are not included in either Weight Empty or Operating Weight Empty tabulation.



A DIVISION OF GENERAL DYNAMICS CORPORATION SAN DIE GO, CALIFORNIA

SPEC NO.: ZD- 22-323			DATE:			
CUSTOMER: Alaska Airlines Inc.			MCL 13.068	DTD 6 J	anuary 196	
CHANGE NO: 13			MODEL: 22-21(#2) (Convair "880")			
TITLE: Periscopic S	extant Provisions	, Wit	h Mount, Insta	allation	of	
ORIGIN: Verbal reque of Convair of	est by Mr. Sindt on 6 January 1961.	f Ala	ska Airlines	to Mr. Ca	rothers	
REASON FOR CHANGE:	Customer request					
EFFECT ON WEIGHT			EFFECT ON BALANCE *			
GUAR, WT, EMPTY	OPER. WT. EMPTY					
+10.0 lbs.	+10.0 lbs.		+2	,891	INCH LB.	
EFFECT ON GUARANTEED P	ERFORMANCE: * None					
* NEGLIGIBLE CHANGES WILL BE ACCUMULATED AND TOTALS REFLECTED IN A FUTURE CHANGE PROPOSAL ACCEPTANCE OF THIS CHANGE IS DEPENDENT UPON PRIOR ACCEPTANCE OF THE FOLLOWING CHANGES:			Attention 1/6/6, ENGINEERING APPROVAL			
LATEST DATE OF ACCEPTANCE:		AIRPL	ANES AFFECTED:			
SPECIAL PROVISIONS:		EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING: TOTAL:				
ACCEPTED:		CONVAIR, A DIVISION OF GENERAL DYNAMICS CORP.				
BY:						
DATE:					104000000000000000000000000000000000000	

Title: Periscopic Sextant Provisions, With Mount; Installation of

Origin: Verbal request by Mr. Sindt of Alaska Airlines to Mr. Carothers of Convair on 6 January 1961.

Reason for Change: Customer request

Description of Change:

Page 45, Add the following new paragraph to the page, after Paragraph 3.14.2.

3.14.2.1 PERISCOPIC SEXTANT (Provisions Only): Provisions shall be made for the later installation of a periscopic sextant in the pilot's compartment. The provisions shall include the installation of a periscopic sextant mount in the top of the fuselage aft of the pilot's overhead panel, installation of overhead trim, lighting and overhead bumpers in the sextant mount area".

Page A-4, APPENDIX I-C, INSTRUMENTS AND RELATED EQUIPMENT:

Add the following item under "FLIGHT INSTRUMENTS"

"1 Mount, Periscopic Sextant Kollsman 1287M-01"

Effect on Weight Empty: +10.0 lbs. Rffect on Balance: +2,891 in 1bs. Effect on Performance: None

A DIVISION OF GENERAL DYNAMICS CORPORATION SAN DIF TO, CALIFORNIA

SPEC NO. ZD- 22-323			DATE:			
CUSTOMER: Alaska Airlines Inc.			MCL 13,008 DTD			
CHANGE NO: 12			MODEL: 22-21(#2) (Convair "880"			
TITLE: Specification 3.17.1.7.1		: Chan	nge (Revision to Paragraph			
ORIGIN: Convair init	tiated					
REASON FOR CHANGE: To	clarify the inter	nt of	Paragraph 3.17.1.7.1.			
EFFECT	N WEIGHT		EFFECT ON BALANCE *			
GUAR, WT. EMPTY	OPER. WT. EMPTY					
0	0		O INCH LB.			
EFFECT ON GUARANTEED P	ERFORMANCE: None	2				
* NEGLIGIBLE CHANGES WIL TOTALS REFLECTED IN A ACCEPTANCE OF THIS CHA PRIOR ACCEPTANCE OF T	FUTURE CHANGE PROPOS ANGE IS DEPENDENT UPO	SAL	FACEASY 2/1, ENGINEERING APPROVAL			
LATEST DATE OF ACCEPTANCE:		AIRPL	ANES AFFECTED:			
SPECIAL PROVISIONS:		EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING: TOTAL:				
ACCEPTED: BY: DATE:		CONVA	AIR, A DIVISION OF GENERAL DYNAMICS CORP.			

Alaska Airlines Inc. Change No. 12

Title: Specification Administrative Change (Revision to Paragraph

3.17.1.7.1)

Origin: Convair initiated

Reason for Change: To clarify the intent of Paragraph 3.17.1.7.1.

Description of Change:

Page 76, Paragraph 3.17.1.7.1 POWER CONTROLS:

Delete the paragraph and substitute the following:

"3.17.1.7.1 POWER CONTROLS: One "NORMAL" and one "ESSENTIAL switch located accessible to both pilots, shall control the ac and dc power to the radio equipment. The "NORMAL" switch shall control the weather radar, the marker beacon, selective call systems No. 1 and No. 2, glide slope No. 2, navigation instrument transformer No. 2, VHF navigation No. 2, radio compass No. 2, VHF communication receiver No. 2, VHF communication transmitter No. 2, HF communication No. 2, DMET No. 1 and No. 2, if installed, and ATC transponder No. 1 and No. 2, if installed. The "ESSENTIAL" switch shall control the VHF communication receiver No. 1, VHF communication transmitter No. 1, VHF navigation No. 1, glide slope No. 1, Radio compass No. 1, navigation instrument transformer No. 1, and HF communication No. 1. The emergency dc bus, through suitable circuit breakers, shall power the audio selector panels, the public address amplifier, the interphone, the pilot compartment speaker, the flight data recorder, and the tape reproducer, if installed. All No. 1 normal radio equipment shall be supplied by a separate ac and dc line. All No. 2 normal radio equipment shall be supplied by a second separate ac and dc line. Protection shall be provided for each line. The power supply, feeder wires, circuit protection for equipment which back up each other functionally shall be separated in a manner that will preclude operation failure of both if any one circuit protective device feeder wire or power supply fails. Illumination shall be provided for the circuit breakers.

Effect on Weight Empty: 0 Effect on Balance: 0 Effect on Performance: None



A DIVISION OF GENERAL DYNAMICS CORPORATION SAN DIEGO CALIFORNIA

SPEC NO.: ZD- 22-323		DATE:				
CUSTOMER Alaska Airlines Inc.			MCL 13,007 DTD			
CHANGE NO 11			MODEL: 22-21(#2)	(Convair "880"		
TITLE: Specificat: Landing Ger	ion Administrative ar Tail Skid)	e Char	nge (Revision to A	uxiliary		
ORIGIN: Convair in:	itiated					
REASON FOR CHANGE: P	roduct improvement					
EFFECT	N WEIGHT		EFFECT ON	BALANCE *		
GUAR. WT. EMPTY	OPER. WT. EMPTY					
0	0		0	INCH LB.		
EFFECT ON GUARANTEED P	ERFORMANCE: None					
* NEGLIGIBLE CHANGES WIL TOTALS REFLECTED IN A ACCEPTANCE OF THIS CHA PRIOR ACCEPTANCE OF TI	FUTURE CHANGE PROPOS ANGE IS DEPENDENT UPO	SAL N	Attenting	Ploth, ERING APPROVAL		
LATEST DATE OF ACCEPTANCE:		AIRPL	ANES AFFECTED:			
SPECIAL PROVISIONS:		EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING: TOTAL:				
ACCEPTED: BY: DATE:		CONVA	IR, A DIVISION OF GENERAL	DYNAMICS CORP.		

Alaska Airlines Inc. Change No. 11

Title: Specification Administrative Change (Revision to Auxiliary

Landing Gear, Tail Skid)

Origin: Convair initiated

Reason for Change: Product improvement

Description of Change:

Page 23, Paragraph 3.8.3 AUXILIARY LANDING GEAR (TAIL SKID):

Change the first line in the paragraph to read as follows:

From: "A retractable skid or"

To: "A skid or"

Effect on Weight Empty: 0 Effect on Balance: 0 Effect on Performance: 0



E DEVISION OF SEMERAL DYNAMICS COMPONATION SAIL DUESO, CALLEON (A.

SPEC NO.: ZD- 22-323			DATE:			
CUSTOMER: Alaska Airlines Inc.			MCL 13,062	DTD	18 October 19	
CHANGE NO: 9			MODEL 22-21	(#2)	(Convair "88	
TITLE: Flight Data	a Recorder, Change	e to V	endor of			
ORIGIN Alaska Air: October 196	lines Letter (SINI	OT to	CAROTHERS) da	ited 1	4	
REASON FOR CHANGE: (Customer request					
EFFECT			EFFE	CT ON B	ALANCE *	
GUAR, WT. EMPTY	OPER, WT. EMPTY					
Negligible	Negligible		Negligi	ble	INCH LB.	
EFFECT ON GUARANTEED P	ERFORMANCE: None					
* NEGLIGIBLE CHANGES WIL TOTALS REFLECTED IN A ACCEPTANCE OF THIS CHAPRIOR ACCEPTANCE OF T	FUTURE CHANGE PROPO ANGE IS DEPENDENT UPO	SAL N	m.L	. (elayto	
			E	NGINEE	RING APPROVAL	
LATEST DATE OF ACCEPTANCE:		AIRPL	ANES AFFECTED:			
SPECIAL PROVISIONS:		EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING: TOTAL:				
ACCEPTED:		CONVA	IR, A DIVISION OF GE	NERAL D	IYN AMICS CORP.	
DATE					7 331 (6) 195073	

Alaska Airlines Inc. Change No. 9

CONVAIR: SD

Title: Flight Data Recorder, Change to Vendor of

Origin: Alaska Airlines Letter (SINDT to CAROTHERS) dated 14

October 1960

Reason for Change: Customer request

Description of Change:

Page 48, Paragraph 3.14.4 FLIGHT DATA RECORDER:

Revise the first sentence as follows:

From: "A Waste King No. 5424 flight data recording system conforming to ARINC Characteristic No. 542 shall be installed."

To: "A United Data Control No. F-542L flight data recorder system, conforming to ARINC Characteristic No. 542, shall be installed."

Page A-4, INSTRUMENTS AND RELATED EQUIPMENT:

Revise the below items under "FLIGHT RECORDER" as follows:

From:	"1	Flight Data Recorder consisting of:	Waste King	5424
		l Encoder (Trip and Data) l Magazine l Recording Unit l Acceleration Sensor	Waste King Waste King Waste King Waste King	10110 5427 100 22 5690"
To:	"l	Flight Data Recorder System, consisting of: 1 Recording Unit 1 Acceleration Sensor 1 Encoder	United Data Control	F-542L"

Effect on Weight Empty: Negligible Effect on Balance: Negligible

Effect on Performance: None

A DIVISION OF GENERAL DYNAMICS CORPORATION SAN DIEGO, CALIFORNIA

SPEC NO.: ZD- 22-323		DATE:				
CUSTOMER: Alaska Air	lines Inc.	MCL 13,064 DTD 28 November 1960				
CHANGE NO: 8		MODEL: 22-21 (#2) (Convair "880")				
TITLE: Passenge	r Seats, Main Cab	in, Change to				
ORIGIN: Alaska A: 3 November	irlines Letter (G	. SINDT to R. B. CAROTHERS) dated				
REASON FOR CHANGE:	Customer request					
	N WEIGHT *	EFFECT ON BALANCE *				
GUAR. WT. EMPTY	OPER, WT. EMPTY					
+390.0 1b	+429.0 lb	+327,773 INCH LB.				
EFFECT ON GUARANTEED P	ERFORMANCE: * None					
* NEGLIGIBLE CHANGES WIL TOTALS REFLECTED IN A ACCEPTANCE OF THIS CHA PRIOR ACCEPTANCE OF TI	FUTURE CHANGE PROPOS ANGE IS DEPENDENT UPO	SAL Attential 16/41				
LATEST DATE OF ACCEPTA	NCE:	AIRPLANES AFFECTED:				
F		EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING: TOTAL:				
ACCEPTED: BY:		CONVAIR, A DIVISION OF GENERAL DYNAMICS CORP.				
DATE:		700 V A1 8,5,0, 6-1217 A				

Alaska Airlines Inc. Change No. 8

Page 1 of 5

Title: Passenger Seats, Main Cabin, Change to

Origin: Alaska Airlines Letter (G. SINDT to R. B. CAROTHERS) dated

3 November 1960.

Reason for Change: Customer request.

Description of Change:

Page 1, Paragraph 1.1 BASIC TYPE:

Revise the second and third sentences to read as follows:

"This specification describes an interior and seating arrangement for the accommodation of 106 passengers; consisting of 94 coach passengers and 12 lounge area passengers. Provisions also are incorporated in this airplane to permit conversion to various mixed seating arrangements and to a full first class seating arrangement."

Page 3b, INTERIOR ARRANGEMENT:

Above illustration will be revised to show an all coach seating arrangement in lieu of first class seating; with the lounge area remaining unchanged.

Page 6, Paragraph 3.1.2.2 TYPICAL LOADING SUMMARY:

Under "Manufacturer's Weight Empty (dry)", change "(Standard Configuration)" to "(Coach Configuration, with 12-Place Lounge)".

In "Fixed Useful Load", change "Life Vests (91)" to "Life Vests (113)".

In "Payload (space limit)*, delete the asterisk and change "(Stand-ard Configuration)" to "(Coach Configuration, with 12-Place Lounge)".

Revise "Space Limit Payloads: " as follows:

From:	"Space Limit Payloads:		Coach
		Standard	Configuration
	Passengers @ 165 lb (84 standard) (105 alter-		
	nate coach)*	13,860	17,325 1b
Kee and the	Baggage @ 40 lb/passenger	3,360	17,325 1b 4,200 1b
	Cargo	5,270	4,430 lb
		22,490	25,955 lb"

Alaska Airlines Inc. Change No. 8

Page 2 of 5

To: "Space Limit Payloads:

Coach Configuration with 12-Place Lounge

Passengers @ 165 1b (94 coach and 12-lounge) Baggage @ 40 lb/passenger Cargo

4,240 1b 4,390 1b 26,120 1b

17,490 1b

Delete the asterisk note on the bottom of Page 6 "(*NOTE: Space limit coach arrangement of)"

Page 9, Paragraph 3.2.1 GENERAL INTERIOR ARRANGEMENTS:

Revise the first sentence as follows:

From: "The standard interior arrangement of this airplane shall be as shown on the inboard plan and profile drawing."

To: "The interior arrangement of this airplane shall be as shown on Page 3b - INTERIOR ARRANGEMENT."

Page 16, Paragraph 3.7.1.3 CREW AND PERSONNEL STATIONS:

Revise the sentence as follows:

From: "The interior arrangement for the standard configuration shall be essentially as shown on the Inboard Profile Drawing herein."

To: "The interior arrangement shall be essentially as shown on Page 3b - INTERIOR ARRANGEMENT."

Page 63, Paragraph 3.16.8.3.4 READING LIGHTS:

Delete the second and third sentences which read as follows:

"Of the five lights provided at each passenger seat row, four shall be instaled in optimum direction for the four abreast standard seating arrangement. The fifth shall be directed toward the center coach seat location."

Delete the last seven words in the fourth sentence "(and placard to clearly indicate its function)"

Alaska Airlines Inc. Change No. 8

Page 3 of 5

Page 79, Paragraph 3.17.2.3.7 SPEAKERS:

In the second line, delete the word "standard".

Page 83, Paragraph 3.19.1 GENERAL:

Revise the paragraph to read as follows:

"The interior shall include furnishings and equipment for 106 passengers (including 12 lounge area passengers) and crew accommodations as shown on illustration herein. In addition, the interior shall be designed to permit conversion to various mixed seating arrangements and to a full first class seating arrangement."

Page 84, Paragraph 3.19.1.1.6 PASSENGER SEATS:

Revise the paragraph to read as follows:

"The passenger seating arrangement shall be as shown on Page 3b -INTERIOR ARRANGEMENT; consisting of 20 double coach seats, 18 triple coach seats and a 12-place lounge area. All passenger seats, except lounge seats, shall have reclinable backs and shall be equipped with plug-in center arm rests in the double seats, and with plug-in arm rests in the triple seat assembly except for the inboard and outboard arm rests which shall be fixed. Stowage provisions for life vests shall be made on the underside of the passenger seats. Space, approximately 10 x 15 x 24 inches shall be provided under each seat in the main cabin for passenger package stow-Integral folding food trays shall be installed in the passenger seat backs excluding last row of seats and the seats immediately forward of the movable coat dividers which shall have provisions only and including cover panels for the food tray wells. Plug-in type food trays shall be provided for the five front row seats, the five seat places just aft of the movable coat dividers and the 12place lounge seats. Stowage for plug-in trays shall be provided in the movable coat dividers. Literature pockets shall be installed on the main cabin forward partitions, the aft side of the movable coat dividers and directly below the food trays in the passenger seat backs."

Page 84, Paragraph 3.19.1.1.6.1 SEAT BACK MOVEMENT:

Revise the two bottom lines as follows:

From: "Normal Vertical: 12 degrees aft of vertical

Recline: 38 and *45 degrees aft of vertical"

Alaska Airlines Inc. Change No. 8

Page 4 of 5

To: "Normal Vertical: 15 degrees aft of vertical

Recline: 23 and 38 degrees aft of vertical"

Delete the note on bottom of Page 84 "(*45 degrees seat recline restricts)"

Page 89, Paragraph 3.19.3.1 GENERAL ARRANGEMENT:

In the first line, <u>delete</u> the word "standard".

Page 89, Paragraph 3.19.3.1.1 PASSENGER COMPARTMENT:

Revise the first sentence as follows:

From: "The main passenger compartment aisle shall be a minimum of 24 inches wide between arm rests in the standard configuration."

To: "The main passenger compartment aisle width shall be approximately 19 inches between arm rests in the coach configuration."

Page 91, Paragraph 3.19.3.6 HAT RACKS:

In the last line, change "Standard" to "Coach".

Page 94a, GASEOUS OXYGEN SYSTEM:

Above illustration will be revised to show 23 seat rows in lieu of 22."

Page A-2, APPENDIX I-B, CUSTOMER FURNISHED - CUSTOMER INSTALLED:

Revise the below item under "Description" as follows:

From: "91 Life Vest 159.0"

<u>To:</u> "113 Life Vest 198.0"

Page A-15, APPENDIX I-C, FURNISHINGS:

Revise the below items under "Description" as follows:

Alaska Airlines Inc. Change No. 8

Page 5 of 5

From: "36 Seats, Double (First Class)

68 Tray, Integral Folding Food

20 Tray, Plug-in Type

84 Belt, Passenger Safety"

To: "18 Seats, Triple, Coach, L.H.

19 Seats, Double, Coach, R.H.

1 Seat, Double, Coach, L.H. 84 Trays, Integral Folding Food

22 Trays, Plug-in Type

106 Belts, Passenger Safety"

Effect on Operating Weight Empty: +429.0 pounds
Effect on Weight Empty: +390.0 pounds
Effect on Balance: +327.772 inch

Effect on Balance: +327,773 inch-pounds

Effect on Performance: None

The following shall not appear in the specification language:

The installation of the coach seats as covered by this proposal will be at 36-inch spacing.

A "Babe in Arms" placard will be installed on the forward left hand partition.

A TIVISION OF GENERAL DYNAMICS CORPORATION SAN DILGO, CALIFORNIA

SPEC NO.: ZD- 22-323		DATE:			
CUSTOMER: Alaska Airlines Inc.		MCL 13,006 DTD			
CHANGE NO. 7			MODEL: 22-21	(#2) (Con	vair "880")
TITLE: Specificati ment Panel	on Administrative Illustration and	Chan to Pa	ge (Revision r. 3.14.2)	to Pilots	' Instru-
ORIGIN: Convair ini	tiated				
,	lo revise subject installation, and compass system swi	to in	dicate correc		
EFFECT ON WEIGHT *			EFFE	CT ON BALAN	ICE *
GUAR, WT. EMPTY	OPER. WT. EMPTY				
0	0			0	INCH LB.
EFFECT ON GUARANTEED PERFORMANCE:					
	None	IB US			
NEGLIGIBLE CHANGES WILL BE ACCUMULATED AND TOTALS REFLECTED IN A FUTURE CHANGE PROPOSA ACCEPTANCE OF THIS CHANGE IS DEPENDENT UPON PRIOR ACCEPTANCE OF THE FOLLOWING CHANGES:				Cla	
				ENGINEERING	APPROVAL
LATEST DATE OF ACCEPTANCE:		AIRPL	ANES AFFECTED:		
SPECIAL PROVISIONS:		EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING: TOTAL:			
ACCEPTED:		CONVAIR, A DIVISION OF GENERAL DYNAMICS CORP.			ICS CORP.
BY:					
DATE:					S SECTION DESIGNATION

Alaska Airlines Inc. Change No. 7

Title: Specification Administrative Change (Revision to Pilots'

Instrument Panel Illustration and to Par. 3.14.2)

Origin: Convair initiated

Reason for Change: To revise subject illustration to agree with

actual installation, and to indicate correct

location of compass system switches.

Description of Change:

Page 43a, PILOT'S AND COPILOT'S INSTRUMENT PANELS:


Replace above illustration in specification with Enclosure (A) which was revised to be in agreement with actual instrument installation.

Page 45, Paragraph 3.14.2 FLIGHT AND NAVIGATIONAL INSTRUMENTS - EQUIPMENT INTERCONNECTION AND DESCRIPTION:

In the third line, change "center engine" to "copilot's"

Enclosure: (A) One copy Page 43a - PILOT'S AND COPILOT'S INSTRU-MENT PANELS (Revised)

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None



A UNISIDE OF GENERAL DENAMICS CORPORATION SAN DIE GO, CALIFORNIA

SPEC NO. ZD- 22-323			DATE:				
CUSTOMER: Alaska Airlines Inc.		ı	MCL 13,005 DT	D			
CHANGE NO: 6			MODEL. 22-21 (#2) (Co	nvair "880		
TITLE Specifica Specifica	tion Administrativ	re Chai	nge (Revision to	Engin	e		
ORIGIN Convair i	nitiated						
REASON FOR CHANGE: T	o specify the G. Ingines will be sup	E. Eng	ine Specificatio	n unde	r which		
· FFFECT ON WEIGHT *			EFFECT O	N BALAN	CE ·		
GUAR. WT, EMPTY				0	INCH LB.		
EFFECT ON GUARANTEED F	PERFORMANCE: * None						
NEGLIGIBLE CHANGES WILL TOTALS REFLECTED IN A ACCEPTANCE OF THIS CH PRIDR ACCEPTANCE OF T	FUTURE CHANGE PROPO IANGE IS DEPENDENT UPO	SAL Mi	Adealy	12/3/6J	APPROVAL		
LATEST DATE OF ACCEPTA	ANCE:	AIRPL	ANES AFFECTED:				
SPECIAL PROVISIONS		EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING: TOTAL:					
ACCEPTED: BY.		CONVA	AIR, A DIVISION OF GENER	AL DYNAM	ICS CORP.		
					SEVALUSSO 671217 A		

Alaska Airlines Inc. Change No. 6

CONVAIR: SD

Title: Specification Administrative Change (Revision to Engine Speci-

fication)

Origin: Convair initiated

Reason for Change: To specify the G. E. Engine Specification under

which engines will be supplied.

Description of Change:

Page 2, Paragraph 2.2 ENGINE SPECIFICATION:

Revise the paragraph as follows:

From: "General Electric Engine Specification E-723h dated

1 September 1959 shall apply.

To: "General Electric Engine Specification E-790 dated 11 July

1960 with Reverser Specification E-725e dated 11 July 1960

and Suppressor Specification E-731f dated 11 July 1960

shall apply.'

Page 4, Paragraph 3.1.1.1 PERFORMANCE:

In the eighth line, change "CJ-905-3B" to "CJ-805-3B".

In the ninth line, change "E-723h, dated 1 September 1959" to "E-790, dated 11 July 1960".

Page A-1, APPENDIX I-A, CUSTOMER FURNISHED - CONVAIR INSTALLED:

Revise the following item under "POWER PLANT EQUIPMENT" as follows:

From: "4 Engine, Complete *(Dry) Gen. Electric CJ-805-3B 12980.0"

To: "4 Engine, Complete *(Dry) Gen. Electric CJ-805-3B 12,980.0"

Spec. No. E-790

dated 7-11-60

Effect on Weight Empty: O Effect on Balance: O Effect on Performance: None

A CIVISION OF GENERAL DYNAMICS CORPORATION SAN DIF GO, CALIFORNIA

SPEC NO.: ZD-22-323		DATE:			
CUSTOMER: Alaska Airlines Inc.		MCL 13,00	4 DTD		
CHANGE NO: 5		MODEL: 22	-21 (#2) (Conva	ir "880	
TITLE Specificatio to Paragraph		ange (Addition	of Static Inve	rter	
ORIGIN Convair init	iated				
REASON FOR CHANGE: T	o specify that sta	ic inverter is	being furnishe	d	
			2		
EFFECT	ON WEIGHT *	EF	FECT ON BALANCE *		
GUAR, WT. EMPTY	OPER, WT, EMPTY				
0	0 . 0		0 11	VCH LB.	
EFFECT ON GUARANTEED F	PERFORMANCE: * None				
* NEGLIGIBLE CHANGES WIL TOTALS REFLECTED IN A ACCEPTANCE OF THIS CH PRIOR ACCEPTANCE OF T	FUTURE CHANGE PROPO ANGE IS DEPENDENT UPO	Jan. e. c	ALWAY 11/21 ENGINEERING APPR		
LATEST DATE OF ACCEPTANCE.		AIRPLANES AFFECTE	ED:		
		EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING: TOTAL:			
ACCEPTED:		ONVAIR, A DIVISION OF	F GENERAL DYNAMICS CO	ORP.	
·BY:					
DATE:			TOWVALL	S. D. BANKEY	

Title: Specification Administrative Change (Addition of Static

Inverter to Paragraph 3.16.2.4.1)

Origin: Convair initiated

Reason for Change: To specify that static inverter is being

furnished

Description of Change:

Page 52, Paragraph 3.16.2.4.1 - POWER TRANSFER:

Add the following to the end of paragraph:

"A static inverter, connected to the battery, shall be provided for engine ground start when external a-c electrical power is not available".

Effect on Weight Empty: 0
Effect on Balance: 0
Effect on Performance: None

A DIVISION OF GENERAL DYNAMICS CORPORATION SAN DIEGO, CALIFORNIA

SPEC NO. ZD-22-323 CUSTOMER: Alaska Air Lines		D	DATE:				
		М	CL 13	,053	DTD		
CHANGE NO: 4		М	ODEL:	22-2	21(#2)	(Con	vair "880
TITLE Main System	Hydraulic Pumps,	Change	to				
ORIGIN Convair init	iated						Taby.
REASON FOR CHANGE:	roduct improvemen	t					
EFFECT	ON WEIGHT .			EFF	ECT ON E	BALANC	E *
GUAR, WT. EMPTY	OPER, WT. EMPTY				T		
+31.0 lbs	+31.0 lbs			+2	3,091		INCH LB.
EFFECT ON GUARANTEED F	PERFORMANCE: * None					Ť.	
NEGLIGIBLE CHANGES WILL BE ACCUMULATED AND TOTALS REFLECTED IN A FUTURE CHANGE PROPOSAL ACCEPTANCE OF THIS CHANGE IS DEPENDENT UPON PRIOR ACCEPTANCE OF THE FOLLOWING CHANGES:		SAL	A	the	ENGINE	PIV/	168 APPROVAL
LATEST DATE OF ACCEPTANCE:		AIRPLAN	IES AFFE	CTED			
SPECIAL PROVISIONS:		EFFECT ON PRICE PER AIRPLANE: RECURRING: NON-RECURRING: TOTAL:					
ACCEPTED:		CONVAIR	, A DIVISIO	ON OF	ENERAL	DYN AMI	CS CORP.
BY:							
DATE:						15 (18)	Wald son skilner

Alaska Air Lines Change No. 4

CONVAIR: SD

Title: Main System Hydraulic Pumps, Change to

Origin: Convair initiated

Reason for Change: Product improvement

Description of Change:

Page A-12, APPENDIX I-C, HYDRAULIC AND PNEUMATIC EQUIPMENT:

Revise the below item under "Description" as follows:

From: "4 Pump, Main System Ham. Standard"

(Variable Displacement

To: "4 Pump, Main System Vickers AS-61695-L-2

(Variable Displacement Type)

Effect on Weight Empty: +31.0 lbs

Effect on Balance: +23091 in. lbs.

Effect on Performance: None

The following shall not appear in the Specification language:

The hydraulic pump will incorporate one electrical depressurization valve and one blocking valve. The bolt-on ports will be modified to suit the Model 22 installation, and the yoke blocked back to a 6 gpm rating in lieu of 10 gpm.

This proposal also deletes the four accumulators in the hydraulic return lines, since these accumulators are not required with the Vickers pump.



A DIVISION OF SENERAL DYNAMICS CORPORATION SAN DIFEO, CALLEGRINA

CUSTOMER. Alaska Airlines Inc.		DATE:	
		MCL 13,003 DTD	
		MODEL: 22-21(#2) (Convair "880")	
TITLE: Specification Ceiling Height		hange (Clarification of Cabin	
ORIGIN: Convair init	iated	v	
	clarify cabin cei iling.	ling in the area of the dropped	
EFFECT	ON WEIGHT .	EFFECT ON BALANCE	
O O O O		O INCH L.B.	
EFFECT ON GUARANTEED	PERFORMANCE: None		
ACCEPTANCE OF THIS CH	LL BE ACCUMULATED AND FUTURE CHANGE PROPOSIANGE IS DEPENDENT UPOTHE FOLLOWING CHANGES:	SAL Anthantine "lules	
LATEST DATE OF ACCEPTA	ANCE:	AIRPLANES AFFECTED:	
RE NO		EFFECT ON PRICE PER AIRPLANE RECURRING: NON-RECURRING. TOTAL:	
ACCEPTED: BY: DATE:		CONVAIR, A DIVISION OF GENERAL DYNAMICS CORP.	
DATE:		1.00000MH-22.0042HW	

Alaska Airlines Inc. Change No. 3

Title: Specification Administrative Change (Clarification of

Cabin Ceiling Height.

Origin: Convair initiated.

Reason for Change: To clarify cabin height in the area of the dropped

ceiling.

Description of Change:

Page 89, Paragraph 3.19.3.1.1 - PASSENGER COMPARTMENT:

Revise the last sentence to read as follows:

"The clear ceiling height in the main cabin shall be approximately 85 inches at the airplane centerline except in the area of the dropped ceiling which shall be approximately 78 inches".

Effect on Weight Empty: 0 Effect on Balance: 0 Effect on Performance: None

A DIVISION OF GENERAL DYNAMICS CORPORATION SAN DIEGO, CALIFORNIA

SPEC NO. 20- 22-323			DATE:	
CUSTOMER: Alaska Airlines Inc.			MCL 13,001 DTD	
CHANGE NO. 1			MODEL: 22-21(/2) (Convair "880")	
TITLE: Specification 3.10.6.3.4 and	n Administrative C	hange Panel	(Revision to Paragraph	
ORIGIN: Convair init:	lated			
REASON FOR CHANGE:	o clarify the int	ent o	f the specification.	
EFFECT	DN WEIGHT .		EFFECT ON BALANCE	
GUAR. WT, EMPTY	OPER, WT, EMPTY			
	O		O INCH LB.	
EFFECT ON GUARANTEED P	ERFORMANCE: *			
* NEGLIGIBLE CHANGES WILL BE ACCUMULATED AND TOTALS REFLECTED IN A FUTURE CHANGE PROPOSAL ACCEPTANCE OF THIS CHANGE IS DEPENDENT UPON PRIOR ACCEPTANCE OF THE FOLLOWING CHANGES:			m. L. clayton	
			ENGINEERING APPROVAL	
LATEST DATE OF ACCEPTANCE: AIRI		AIRPL	ANES AFFECTED:	
RECU NON-1		RECUR NON-RE	FFECT ON PRICE PER AIRPLANE: ECURRING: ION-RECURRING: OTAL:	
ACCEPTED:		CONVA	IR, A DIVISION OF GENERAL DYNAMICS CORP.	
BYs				
DATE:			CONVERGED SEVERA	